

Report ID: 26,697,166 1 Version: 19 May 2025 Created:

Make:	Honda	Model:	FIT	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	<b>Registration:</b>		<b>Reg Expiry:</b>		Engine	•	-	
WoF Expiry:	12 May 2026	Odometer:	71,997 Kms	Good No:	26697166	Oil level	~		
VIN:	7AT08G2YX25059096	Next Service:	82000	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside		for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged ic	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				20		Operation	~		
PT = paint defe	ect NP	Ir I			1111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				2414	CV joints	~		
* = decals	- dle	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
,, significall		C			Р	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7.0 mm		mm
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compate						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Buckley Date: 19 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....