

Kms:

I have read and understood this condition guide. Name:

Cambelt

Dry

No

Road Conditions During Test Drive:

Evidence of Cam Belt Replacement:

Imraan Bryant

Engine Timing Mechanism:

Inspected by:

01 Apr 2025 Date:

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Signature:

V

V

V

V

WoF Expiry:	25 Apr 2026	Odometer:	101,890 Kms	Good No: 2	6700597	Oil level
VIN:	MPBUMFF60MX321193	Next Service:	111,000 km	Service History:	Yes	Smoke & fumes
NI / 1911						Performance
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise
						Cooling System
						Coolant condition
	SC D P P SC W					
Key: S = scratch						Radiator / Hoses (visu
						Transmission
R = rust						
PT = paint defect						Noise
C = crack						
P = pin dent						CV joints
* = decals						
SC = stone chips W = significant scuffs Body Inspection Comments R/R tail light scratched,R/R&L/R inner door jam pin dent,Windscreen stone chip in&out cva,						Brakes
						Performance
						Hand Brake
						Tyres (lowest observed
						Left front
						Right front
						Left rear
Conditions During Body Inspection: Dry						Right rear
						Spare
Under Carriage & Under Bonnet Inspection Comments						Suspension
RWD,						Suspension performa
						Steering performance
						Shock absorbers