

Basic Vehicle Condition Guide

Report ID: 26,702,143


Version: 3

Created: 11 May 2025

Make: Model: Nissan Leaf **Body Style:** Hatchback Year: 2016 Registration: NJJ11 Reg Expiry: 05 Aug 2025 **Odometer:** WoF Expiry: **Good No:** 12 Apr 2026 81,873 Kms 26702143 VIN: 7AT0DH8KX21212131 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body hispection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

2wd

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

SOH 70.%(9 bar left) 24X

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 02 Apr 2025

Name:

| | Pass | Fail | N/A | | |
|------------------------------|-----------------------|---------|---------------------------------------|--|--|
| Engine | | | | | |
| Oil level | | | ~ | | |
| Smoke & fumes | ~ | | | | |
| Performance | ~ | | | | |
| Noise | V | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | V | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | 3 | .0 | mm | | |
| Right front | 3.0 | | mm | | |
| Left rear | 4.0 | | mm | | |
| Right rear | 4.0 | | mm | | |
| Spare | | N/A | | | |
| Suspension | | 1 | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | - | | | | |
| Dashboard warning lights | ' | | | | |
| Wipers (front & rear) | V V V V V | | | | |
| Window winder FL | • | | | | |
| Window winder FR | • | | | | |
| Window winder RL | • | | | | |
| Window winder RR | • | | | | |
| Rear view mirrors | | | | | |
| Radio (basic test only) | / | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | | | | |
| Central locking | ' | | | | |
| Remote locking | | | | | |
| Sat. Nav. (basic test only) | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Reversing camera | | | | | |

Signature: