

Basic Vehicle Condition Guide

Report ID: 26,702,209


Version:

05 Apr 2025 Created:

Make: Volkswagen Model: Beetle **Body Style:** Hatchback Year: 2009 Registration: EUG97 **Reg Expiry:** 10 Feb 2026 **WoF Expiry: Odometer:** 18 Apr 2026 113,114 Kms **Good No:** 26702209 WVWZZZ9CZ8M560270 VIN: **Next Service:** 120000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips on windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

<u>Interior Comments</u>	
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Fabric coming off doors

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Fail N/A Pass Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front 5.0 mm Right front 5.5 mm Left rear 5 mm 5 Right rear mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR 1 Window winder RL Window winder RR ~ Rear view mirrors / Radio (basic test only) 1 CD (basic test only) / Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~

Reversing camera

1

Signature:

31 Mar 2025 Jaykib Collins Inspected by: Date:

Name: