

Report ID: 26,702,906 1 Version: 17 Apr 2025 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	HYA913	Reg Expiry:	01 Nov 2025	Engine			
WoF Expiry:	13 Aug 2025	Odometer:	135,561 Kms	Good No:	26702906	Oil level	~		
VIN:	WF0EXXGBBEEP80174	Next Service:	145000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	or an additional o	narge.	Coolant condition	~		
	S W				S	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			210	HILS	Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack				TTY I		Clutch			~
P = pin dent	s sc dl				2416	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
		S	S S		S	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Minor stone chips on windscreen						Left front	5	.5	mm
						Right front	5	.5	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
						Spare Yes			
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Tir	ning Machanism	Timina	Chain			Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jaykib Collins Date: 02 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: