

Report ID: 26,702,934 1 Version: 08 Apr 2025 Created:

Make:	Audi	Model:	Q3	Body Style:	SUV		Pass	Fail	N/A
Year:	2012	Registration:	GLY614	Reg Expiry:	28 Feb 2025	Engine	1	I	
WoF Expiry:	06 Jan 2025	Odometer:	157,243 Kms	Good No:	26702934	Oil level	~		
VIN:	WAUZZZ8U3CR039137	Next Service:	167000	Service Histor	/: Yes	Smoke & fumes	r		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	ransmission		
D = dent R = rurt						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 00						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	
No parcel tray						Left front	Tyres (lowest observed tread depth of tyres) Left front 6.0		
						Right front		.0	mm mm
						Left rear			mm
								.0	
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder earlage a onder bonnet inspection comments						Suspension			
Tested batt	ery and passed. Runs or	n diesel fuel. Veh	icle has belly pans.			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	,					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	ird Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Consul						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Air conditioning and heating systems ok at inspection time. No reverse camera or navigation system						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	v		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Gary Adams						Date: 31 Mar 2025			
Inspected by: Gary Adams Date: 31 Mar 2025									
I have read and understood this condition guide. Name:									