

Report ID: 26,704,283 Version: 1 Created: 04 Apr 2025

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	Registration:	EGT243	Reg Expiry:	07 Sep 2025	Engine			
WoF Expiry:	28 Jan 2026	Odometer:	244,753 Kms	Good No:	26704283	Oil level	~		
VIN:	KMHSH81WR8U267106	Next Service:	250,000km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
					C 144	Performance	~		
Key:	S SC	-0	S D W S SC W	-161-	S W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S SC W						Operation	~		
						Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals SC QQ						Wheel bearings	~		
SC = stone chips						Brakes	v		
W = significant scuffs SSC W SW SRW W SD						Performance	~		
Note: come defecte % blomiches may not be displayed in the dispran						Hand Brake	~		
Body Inspection Comments							•	ofture	
Front right parking light not working						Tyres (lowest observed tread depth of tyres)			
Windscreen stone chips						Left front	4		mm
						Right front	4		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Excessive Engine oil leaks						Suspension performance	~		
Underbody surface rust						Steering performance	~		
4 wheel drive						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deskie	rd .					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
ч Г						•			
Inspected by: Rowan Fey Date: 04 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: