

Report ID: 26,704,491 3 Version: 12 Jun 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2009	Registration:	KRP114	Reg Expiry:	11 Jan 2026	Engine			I
WoF Expiry:		Odometer:	128,335 Kms	Good No:	26704491	Oil level	~		
VIN:	7AT0GF09X17002737	Next Service:	138325	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		c	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	PT SC PT		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ssc dl			The	EID S	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack					SC	Clutch	•		~
P = pin dent	Ho					CV joints	~		
* = decals	sc 916			AL.	EITR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S PT SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments		le delects à blemisties	indy not be disp	ayed in the diagram	Tyres (lowest observed tread	, the second sec	ofturo	() ()
Minor stone chips on windscreen									.s)
						Right front Left rear	6.		mm
							5.		mm
Conditions During Body Inspection: Dry						Right rear	5.5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage a onder bor	meenspeere	<u>eominents</u>			Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
Engine Tir	ning Mochanism	Cambal				Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 105,588						Sat. Nav. (basic test only)			~
Evidence	or Cam Bert Replac	ement: Y	es	Kms: 1()5,588	Reversing camera			~
Inspected	d by: Jaykib Collins					Date: 02 Apr 202	25		

I have read and understood this condition guide.

Name:

Signature: