

Report ID: 26,707,388 4 Version: 14 May 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:		Reg Expiry:		Engine		L	
WoF Expiry:	30 Apr 2026	Odometer:	64,711 Kms	Good No:	26707388	Oil level	~		
VIN:	7AT0GF09X25032533	Next Service:	74,700 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	charge.	Coolant condition	~		
						Performance	V		
Key:		=		5(0)-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
						Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				2414	CV joints	~		
*= decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
					Left front	7.0 m		mm	
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Wet					Right rear	7.0 mm			
					Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD,						Suspension performance	~		
,						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Daabbaa						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Imraan Bryant Date: 02 May 2025									

I have read and understood this condition guide.

Name:

Signature: