

Report ID: 26,708,710 Version: 1 04 Apr 2025 Created:

Make:	Peugeot	Model:	3008	Body Style:	SUV		Pass	Fail	N/A
Year:	2022	Registration:	PMA401	Reg Expiry:	13 Sep 2025	Engine			
WoF Expiry:	24 Aug 2025	Odometer:	24,187 Kms	Good No:	26708710	Oil level	~		
VIN:	VF3M45GYWNS095736	Next Service:	33300 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent R = rust	- HA			The		Operation	~		
PT = paint def	ect NP	IT I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIS				74 <u>11</u> 4	CV joints	~		
* = decals	- Alt			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			D			Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	3 mm		mm
						Right front	4	1	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD						Suspension performance	<		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	ird Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		ļ
<u>General Comments</u>						Window winder RL	~		
W/S crack in	n CVA.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
L						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking									
Engine Ti	ming Mechanism:	Timina				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
		.cmcnt. N		11113.		Reversing camera	~		
Inspected by: Eleoit Kumar Date: 04 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: