

Report ID: 26,709,227 1 Version: 08 Apr 2025 Created:

Make:	Hyundai	Model:	Staria Load	Body Style:	Van		Pass	Fail	N/A
Year:	2023	Registration:	QCR841	Reg Expiry:	30 Aug 2025	Engine			
WoF Expiry:	31 Aug 2026	Odometer:	19,406 Kms	Good No:	26709227	Oil level	~		
VIN:	KMFYFX71MPU136024	Next Service:	15,000 kms (2024)	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
					S	Performance	~		
Key:	S	-0	s s	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sc w			715	HILS	Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan			S S		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			s)
It was raining during inspection, unable to have a good look at the body panels.						Left front	6 mm		
						Right front	6	;	mm
						Left rear	7	,	mm
Conditions During Body Inspection: Wet						Right rear	7 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Now all these signs of damage undercarriage.						Suspension performance	~		
	5 5	5				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dachhar	rd c i					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
]	Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
Oil service.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet							~		
Engine Timing Mechanismy Unknown						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Koonwaiyou Date: 08 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: