

Report ID: 26,711,601 Version: 1 13 Apr 2025 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	DDY468	<b>Reg Expiry:</b>	08 Aug 2025	Engine	1		
WoF Expiry:	04 Oct 2025	Odometer:	145,672 Kms	Good No:	26711601	Oil level	~		
VIN:	WBAVC36030NC56688	Next Service:	155000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
			DD			Performance	V		
Key:						Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
*=decals						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs W S						Performance 🖌			
Rody Inspection Commonts Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	V		
Body Inspection Comments						Tyres (lowest observed tread	(lowest observed tread depth of tyres)		
No spare tyre, no puncture repair kit, no tools, no jack						Left front	6.0 mm		
Minor stone chips on windscreen						Right front	6	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Wet						Right rear	3.	.5	mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel drive						Suspension performance	~		
inear wheel	unve					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories	1		
Seats	Good					Head lights	~		
						Tail lights	V		
Carpets	Good					Indicators	V		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Radio screen is difficult to use as you cannot see properly						Window winder RR	~		
Freshly Serviced						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		·
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jaykib Collins						Data: 02 Apr 2025			
Inspecte	Date: 03 Apr 20	20							
I have read and understood this condition guide. Name:									