

Evidence of Cam Belt Replacement: No	Kms:
Inspected by: Imraan Bryant	
I have read and understood this condition guide.	Name:

Cambelt

Wet

Dashboard

**General Comments** 

Good

Driver seat torn, left front tyre edge starting to wear.

**Road Conditions During Test Drive:** 

Engine Timing Mechanism:

Date: 16 Apr 2025

Window winder FL

Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Signature: .....

V

V

V

V

1

V

2 ✓

V

V

1

V