

Basic Vehicle Condition Guide

Report ID: 26,713,441


5 Version:

15 Apr 2025 Created:

Make: Model: Mazda CX-9 **Body Style:** SUV Year: 2021 Registration: NMZ371 Reg Expiry: 25 May 2025 WoF Expiry: **Odometer: Good No:** 25 Apr 2026 62,740 Kms 26713441 VIN: JM0TC4WLA0045399 Next Service: 72000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD,

| <u>Interior Comments</u> | | |
|--------------------------|------|--|
| Seats | Good | |
| Carpets | Good | |
| Panels | Good | |
| Dashboard | Good | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Imraan Bryant 07 Apr 2025 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|------------------------------|-----------------------|---------|----------|--|--|
| Engine | 1 033 | ı alı | IN/A | | |
| Oil level | ' | | | | |
| Smoke & fumes | | | | | |
| Performance | <i>y y</i> | | | | |
| Noise | <i>'</i> | | | | |
| Cooling System | _ | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | V | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | l depth | of tyre | es) | | |
| Left front | 7 | .0 | mm | | |
| Right front | 7.0 | | mm | | |
| Left rear | 8.0 | | mm | | |
| Right rear | 8.0 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | <i>V</i> | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | V V V V V | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ' | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | ~ | | | | |
| Reversing camera | ' | | | | |
| | | | | | |

Signature: