

Report ID: 26,715,420 4 Version: 24 Apr 2025 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	Registration:	PBQ590	Reg Expiry:	22 Jun 2025	Engine			
WoF Expiry:	08 May 2026	Odometer:	127,690 Kms	Good No:	26715420	Oil level	~		
VIN:	7AT0DH6MX21014979	Next Service:	137,725	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S SC W		S SC S SC	S	S SC	Performance	~		
Key:	1330	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S SC			710	S SC	Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack						Clutch			~
P = pin dent	s sc dle				74116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurrs S SC S SC S SC W S SC						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front	3.	5	mm	
						Right front	3.	5	mm
						Left rear	5.	0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	A					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd 4					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Uriah Pepene Date: 07 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: