

Report ID: 26,716,048 3 Version: 14 Jun 2025 Created:

| Make: | Polestar | Model: | Polestar 2 | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|--|----------------------|--|--------|------|----------|
| Year: | 2022 | Registration: | PJC387 | Reg Expiry: | 27 Jun 2025 | Engine | | | L |
| WoF Expiry: | 03 Jun 2026 | Odometer: | 48,590 Kms | Good No: | 26716048 | Oil level | | | ~ |
| VIN: | LPSVSEGAKNL072247 | Next Service: | 0 | Service Histor | y: No | Smoke & fumes | | | ~ |
| | | | | | | Performance | | | ~ |
| | port is not a warranty | oration is made | for age and mileage | Parts have not | been dismontled or | Noise | | | ~ |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional o | harge. | Coolant condition | | | ~ |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | s dis | | | 715 | HIV | Operation | ~ | | |
| PT = paint defe | ect NP | r I | | $\left(\left \left(\right) \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIG | | | | 74116 | CV joints | ~ | | |
| * = decals | - Alt | | | To . | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| w = significan | S | | | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 6. | .0 | mm |
| | | | | | | Right front | 6. | .0 | mm |
| | | | | | | Left rear | 6. | .0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 6.0 mm | | mm |
| | | | | | | Spare Yes | | | |
| <u>Under Ca</u> | rriage & Under Bor | nnet Inspectio | on Comments | | | Suspension | | | |
| FWD | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Connet | | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dachher- | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | - . | | | | | Window winder FR | ۲ | | |
| General Comments | | | | | Window winder RL | ~ | | | |
| Charger Not With the vehicle | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | <u> </u> |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | <u> </u> |
| Enging Ti | ming Mechanism: | م د ا مرا ا | (D) | | | Remote locking | ~ | | <u> </u> |
| - | - | Unknow | | Knass | | Sat. Nav. (basic test only) | ~ | | <u> </u> |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspecte | d by: Eleoit Kumar | | | | | Date: 13 May 20 | 25 | | |
| L | * | | | | | • | | | |

I have read and understood this condition guide.

Name:

Signature: