

Report ID: 26,718,168 2 Version: 10 Apr 2025 Created:

Make: Mi	ini	Model:	Cooper	Body Style:	Hatchback		Pass	Fail	N/A
Year: 20	007	Registration:	EZH572	Reg Expiry:	09 Jul 2025	Engine			
WoF Expiry: 04	1 Apr 2026	Odometer:	152,117 Miles	Good No:	26718168	Oil level	~		
VIN: WN	WWMF720X0TT34361	Next Service:	162000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	<u>rt is not a warranty</u> guide only Conside	ration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanical	l inspection prior to	purchase and th	his can be arranged f	or an additional c	harge.	Coolant condition	~		
			S SC			Performance	~		
Key:		$-\infty$		500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
B = rust	sc			210	HILLS	Operation	~		
PT = paint defect	NIM				70111	Noise	~		
C = crack					S	Clutch	~		
P = pin dent	sc dB			$\langle \rangle$	74116	CV joints	~		
* = decals	- AK	10		100		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w – significant sci			S		PT	Performance	~		
Body Inspec	ction Comments	Note: som	e defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	mm		
						Right front	4.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboard	Average					Window winder FL	~		
						Window winder FR	۲		
<u>General Comments</u>						Window winder RL			~
Partial service history						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	2		
						Number of keys	1		
Road Condit	tions During Test	Drive:	Dry			Central locking	٢		
		 · · ·				Remote locking	٢		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of (Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by	y: Sione Mae					Date: 08 Apr 20	25		
Inspected D	y. Sione mae					Date. 00 Apr 20			

I have read and understood this condition guide.

Name:

Signature: