

Report ID: 26,718,303 Version: 1 11 Apr 2025 Created:

| Make: | Mitsubishi | Model: | Mirage | Body Style: | Hatchback | | Pass | Fail | N/A | |
|--|---|----------------------|------------------------|---------------------|----------------------|--------------------------------------|--------|--------|-----|--|
| Year: | 2021 | Registration: | NKG36 | Reg Expiry: | 06 Oct 2025 | Engine | 1 | | | |
| WoF Expiry: | 10 Apr 2025 | Odometer: | 56,127 Kms | Good No: | 26718303 | Oil level | ~ | | | |
| VIN: | MMAXTA03AMH001009 | Next Service: | 70,000 | Service Histor | y: No | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty | oration is made | for age and mileage | Parts have not | been dismontled or | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | ical inspection prior to | purchase and th | nis can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | | |
| | | | | | | Performance | ~ | | | |
| Key: | S | $-\infty$ | s s | -161- | SP | Radiator / Hoses (visual) | ~ | | | |
| S = scratch | | | | | | Transmission | | | | |
| D = dent | sscw 616 | | | The | SD SD | Operation | ~ | | | |
| R = rust PT = paint defe | | | | \prod | | Noise | ~ | | | |
| C = crack | | | | $+ \mathbf{\nabla}$ | S R SC | Clutch | • | | ~ | |
| P = pin dent | | | | | 게비 | CV joints | ~ | | | |
| * = decals | SRSC 91 | | | The | ETTE | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs S S P S S P S | | | | | | Performance | ~ | | | |
| | | Note: som | e defects & blemishes | may not be disc | laved in the diagram | Hand Brake | ~ | | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Tyres (lowest observed tread | • | oftvre | | |
| Cracked stone chips in windscreen | | | | | | Left front 5 mm | | | | |
| | | | | | | Right front | 5. | | mm | |
| | | | | | | Left rear | | | mm | |
| | | | | | | Right rear | | | | |
| Conditions During Body Inspection: Dry | | | | | | | 4.5 mm | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes Suspension | | | | |
| | | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | | V | | | |
| | | | | | | Air Conditioning / Heater | | | | |
| Interior Comments | | | | | | Operation Electrical / Accessories | | | | |
| | | | | | | | | | | |
| Seats | Good | | | | | Head lights | ~ | | | |
| Carpets | Good | | | | | Tail lights | ~ | | | |
| | | | | | | Indicators | ~ | | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | | |
| | | | | | | Window winder FL | ~ | | | |
| General | <u>Comments</u> | | | | | Window winder FR | ~ | | | |
| | | | | | | Window winder RL | ~ | | | |
| | | | | | | Window winder RR | ~ | | | |
| | | | | | | Rear view mirrors | ~ | | | |
| | | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | | | ~ | |
| | | | | | | Number of keys | 2 | | | |
| Road Conditions During Test Drive: Dry | | | | | | | ~ | | | |
| - Engine Ti | ming Mechanism | Timina | - | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence | or Cam Beit Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | | |
| Inspector | Inspected by: Samuel Weir Date: 11 Apr 2025 | | | | | | | | | |
| | | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: