

Report ID: 26,719,564 3 Version: 04 Jun 2025 Created:

Make:	Holden	Model:	Astra	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2018	Registration:	LLC52	Reg Expiry:	10 Jun 2025	Engine	1		1	
WoF Expiry:	12 Mar 2026	Odometer:	90,000 Kms	Good No:	26719564	Oil level	~			
VIN:	KL3BM5EMXHK628698	Next Service:	96,957 Kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~			
	W		D			Performance	~			
Key:		-0		500-		Radiator / Hoses (visual)	V			
S = scratch D = dent						Transmission				
						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
* = decals						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
Front right tyre has sidewall damage						Left front	6.4 mm		mm	
						Right front	6	.4	mm	
						Left rear	6	.8	mm	
Conditions During Body Inspection: Wet						Right rear	6.8 mr		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension					
Front crossmember and engine on sump surface rust						Suspension performance	~			
						Steering performance	~			
	Shock absorbers	~								
						Air Conditioning / Heater	Conditioning / Heater			
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Slight wea	r on drivers seat				Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
L						Window winder FR	~			
General Comments						Window winder RL	~			
Partial service history						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Wet Centra							~			
Remote locking							~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Hoani Saunders Date: 03 Jun 2025										

I have read and understood this condition guide.

Name:

Signature: