

Report ID: 26,721,120 3 Version: 09 Apr 2025 Created:

Make:	Ford	Model:	Fiesta	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GQQ187	Reg Expiry:	30 Jun 2025	Engine	I		L
WoF Expiry:	10 Dec 2025	Odometer:	55,741 Kms	Good No:	26721120	Oil level	~		
VIN:	MNBJXXARJJCC15237	Next Service:	70000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S SC		S W		SP	Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			L
R = rust	sw			20		Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	PT				74IIL	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan			S S		S	Performance	~		
Body Insi	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
Paint fade on roof and bonnet.						Left front 6 n			mm
						Right front	e	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare No			
Under Ca	irriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
r						Operation	~		
Interior Comments						Electrical / Accessories			L
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	•					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Vehicle drove well.					Window winder RR	~			
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
						-	-		
Inspecte	d by: Jayden Roxburg	jh				Date: 09 Apr 20	25		

I have read and understood this condition guide.

Name:

Signature: