

Report ID: 26,723,229 7 Version: 03 Jul 2025 Created:

Make:	Volkswagen	Model:	EOS	Body Style:	Convertible		Pass	Fail	N/A	
Year:	2008	<b>Registration:</b>	KQK487	Reg Expiry:	15 Oct 2025	Engine	1			
WoF Expiry:	24 Apr 2026	Odometer:	92,310 Kms	Good No:	26723229	Oil level	~			
VIN:	WVWZZZ1FZ7V007852	Next Service:	102,300kms	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
					DP	Performance	~			
Key:		-0	S D PT P	S S		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent R = rust SSC D A						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~		-	
* = decals DSC 000 SW						Wheel bearings	~			
SC = stone chips						Brakes	Brakes			
W = significant scuffs S S P S P S P						Performance	~			
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
Body Inspection Comments							Tyres (lowest observed tread depth of tyres)			
Letter "S" and "I" are missing off badges on boot lid.						Left front 5.6 mm				
						Right front	6	-	mm	
						Left rear		.0	mm	
Conditions During Body Inspection:						Right rear		.0	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation				
Interior Comments						Electrical / Accessories				
Seats Good						Head lights				
						Tail lights	· ·			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	1					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~	
Inspected by: Jason Young Date: 12 Apr 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....