

Report ID: 26,724,382 1 Version: 10 Apr 2025 Created:

Make:	Suzuki	Model:	Baleno	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2021	Registration:	NJZ828	Reg Expiry:	05 Oct 2025	Engine	1	I	
WoF Expiry:	10 Apr 2026	Odometer:	49,818 Kms	Good No:	26724382	Oil level	~		
VIN:	MBHEWB42S00621743	Next Service:	49000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			S SD			Performance	V		
Key:		-0		500-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission	mission		
B = rust SSC DA						Operation	~		
PT = paint defe	ect NP				111/1	Noise	V		
C = crack						Clutch			~
P = pin dent	sc dle				24116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant			S D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
					Left front	2.0 mm		mm	
						Right front	2	.5	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front wheel drive						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Due for a se	rvice					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
Number of keys							2		
Road Conditions During Test Drive: Dry							~		
Enging Ti	ning Machanism	T:	- 			Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Jaykib Collins Date: 09 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: