

Report ID: 26,725,277 2 Version: 01 May 2025 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	<b>Registration:</b>	NHE180	<b>Reg Expiry:</b>	08 Aug 2025	Engine	•	•	
WoF Expiry:	04 Feb 2026	Odometer:	133,276 Kms	Good No:	26725277	Oil level	~		
VIN:	KMHS381HWMU349799	Next Service:	140000 kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged to	or an additional of	inarge.	Coolant condition	~		
	Р		PP			Performance	~		
Key:				500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			10	Elle	Operation	~		
PT = paint defe	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				2416	CV joints	~		
* = decals	- dle	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant	PT	<b>O</b>	P	S		Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
LR door sill scratch and dent. RR door sill scratch.						Left front	Left front 3		
						Right front	3 mm		mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
4WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	driver doc	or panel dent.				Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)							~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Eleoit Kumar Date: 01 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....