

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance SC S SC S PT Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S SC Operation V R = rustNoise V PT = paint defect C = crackClutch V P = pin dent CV joints V S D SC * = decals S PT Wheel bearings V SC = stone chips Brakes W = significant scuffs SC S SC SC Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V Body Inspection Comments Tyres (lowest observed tread depth of tyres) Both front wing mirrors paint is peeling off Left front 6.8 mm **Right front** 5.2 mm Left rear 6.3 mm **Right rear** 7.2 mm Conditions During Body Inspection: Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V No underbody inspection Steering performance V Shock absorbers V Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Head lights Seats 1 Good Tail lights ~ Carpets Good Indicators ~ Dashboard warning lights 1 Panels Good V Wipers (front & rear) Dashboard Good Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) ~ Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism:** Cambelt Sat. Nav. (basic test only) ~ Evidence of Cam Belt Replacement: Kms: No Reversing camera ~ Melissa Wilson 02 May 2025 Inspected by: Date:

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,726,555 1 Version: 02 May 2025 Created:

Pass

~

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

Fail

N/A