

Report ID: 26,727,107 2 Version: 19 Apr 2025 Created:

Make:	Holden	Model:	Barina	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	CTN477	Reg Expiry:	25 Sep 2025	Engine	1	i	
WoF Expiry:	24 Dec 2025	Odometer:	106,241 Kms	Good No:	26727107	Oil level	~		
VIN:	W0L0XCF0854138640	Next Service:	112,000km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		W		S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	sc w			715	HIL PT W	Operation	~		
PT = paint defe		F I		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	HIC				7414	CV joints	~		
* = decals	PT SC 916			- Jul	ELD SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs SC W	$\neg \varnothing$	S		DW	Performance	~		
Deduction		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tvre	es)
Windscreen stone chips						Left front	· · · · · · · · · · · · · · · · · · ·		
Moisture in	boot					Right front		.0	mm
						Left rear		.0	mm
Conditions During Pody Inspection:						Right rear	3.0 mm		-
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Engine oil le Front whee						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		$\left  \right $
Danala						Dashboard warning lights	~		├
Panels	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		+
General C	<u>Comments</u>					Window winder RL	-		~
						Window winder RR			~
·						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	v v		
						Number of keys	2		L
							2		
Road Conditions During Test Drive: Dry Central locking   Remote locking Remote locking								~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)								~	
Evidence of Cam Belt Replacement: Not Applicable Kms:									<b>v</b>
		IV				Reversing camera			~
Inspected by: Rowan Fey Date: 15 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....