

Report ID: 26,727,202 2 Version: 11 May 2025 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	HPK41	Reg Expiry:	07 Jul 2025	Engine			
WoF Expiry:	22 Apr 2026	Odometer:	84,075 Kms	Good No:	26727202	Oil level	~		
VIN:	7AT0C12HX13275113	Next Service:	94000	Service Histor	y: No	Smoke & fumes	~		
Net a This was						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
	ical inspection phot to	purchase and ti	is can be analiged to		indige.	Coolant condition	~		
Kara	S S	\sim	S S		S	Performance	<		
Key: S = scratch		\sim (0)		5(O)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	AIA			10	All	Operation	~		
PT = paint defe	ect NP	1				Noise	~		
C = crack				\square		Clutch			~
P = pin dent	sc dk				24145	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	S S	\sim	S P	S	W	Performance	۲		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	0	mm
						Right front	6.	0	mm
						Left rear	5.	0	mm
Conditions During Body Inspection: Dry						Right rear			
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		ļ
Carpets	Good					Tail lights	~		
						Indicators	~		ļ
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	0000					Window winder FL	~		
Comorrol						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ning Machanism	Time !:== - 1	- 			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	d by: John Koonwaiyo	ou				Date: 11 Apr 202	25		
Date: 11 Apr 2023									

I have read and understood this condition guide.

Name:

Signature: