

Report ID: 26,729,318 1 Version: 22 Apr 2025 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	MLF240	Reg Expiry:	30 Jun 2025	Engine			
WoF Expiry:	14 May 2025	Odometer:	128,604 Kms	Good No:	26729318	Oil level	~		
VIN:	JMFXTGF8WKZ009393	Next Service:	133,114	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional o	narge.	Coolant condition	~		
	SC W		SC SC			Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc			10	S PT W	Operation	~		
PT = paint defe	ect NP	1				Noise	~		
C = crack				TTX.	R SC	Clutch			~
P = pin dent	RSC de				241 <u>16</u>	CV joints	~		
* = decals		1 O		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
, significan	SC W		SC P SC	W		Performance	~		
Body Inst	pection Comments	Note: som	e defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
<u> </u>						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.5	mm
						Right front	5.	.5	mm
						Left rear	2.	.5	mm
Conditions During Body Inspection: Dry						Right rear	2.5 mm		mm
						Spare Yes			
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	6000					Window winder FL	~		
Canada						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry							1		
						Remote locking	~		
-	ming Mechanism:	Unknow				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Tyler Le Bherz Date: 22 Apr 2025									
Inspected by: Tytel Le biletz Date: 22 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: