

Report ID: 26,731,591 Version: 1 14 Apr 2025 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	MFG135	Reg Expiry:	26 Jun 2025	Engine			
WoF Expiry:	19 Dec 2025	Odometer:	285,005 Kms	Good No:	26731591	Oil level	~		
VIN:	MMAJLKL10LH00666(Next Service:	286000km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				TIN	HIL S	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	110				게止	CV joints	~		•
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D S						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	layed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	(s)
Windscreen is cracked inside and outside the CVA.								mm	
						Right front	1		mm
						Left rear	5		mm
			_			Right rear			
Conditions During Body Inspection: Dry						Spare	<u> </u>		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
							-		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	drivers sea	at base pad is tor	n/worn			Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	centre con	nsole lid is torn/w	vorn.			Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
4WD.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Haden Brown Date: 14 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: