

Report ID: 26,732,889 Version: 1 16 Apr 2025 Created:

Make:	Nissan	Model:	Note	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2013	Registration:	PRY70	Reg Expiry:	10 Jul 2025	Engine				
WoF Expiry:		Odometer:	126,780 Kms	Good No:	26732889	Oil level	~		1	
VIN:	7AT0DH79X22156525	Next Service:	-	Service Histor		Smoke & fumes	~		+	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				,	Performance	~		+	
	port is not a warranty		с I II			Noise	~		+	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~		+	
Key:	SC	-0	SW W		s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	ISC 6/6			11-	EID S	Operation	~		1	
R = rust				1 M	JHIH	Noise	~		+	
PT = paint def C = crack	ect			+	SC	Clutch			~	
P = pin dent	Ho					CV joints	~			
* = decals	sc pp					Wheel bearings	-		+	
SC = stone chips						Brakes	~			
W = significant scuffs SC D D D S						Performance			T	
Note come defects ? blamiches may not be displayed in the diagram							~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake				
						Tyres (lowest observed tread depth of tyres)				
						Left front		.0	mm	
						Right front		.0	mm	
						Left rear	-	.0	mm	
Conditions During Body Inspection: Dry						Right rear	3	3.0 mm		
Linder Carriage & Linder Perpet Instruction Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Battery pas	sed test.					Suspension performance	~		<u> </u>	
						Steering performance	~		<u> </u>	
						Shock absorbers	~			
						Air Conditioning / Heater		1		
Interior Comments						Operation	~			
Interior Comments						Electrical / Accessories	1	1		
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~		<u> </u>	
Dashboa						Wipers (front & rear)	~		<u> </u>	
Dashbud	Good					Window winder FL	~			
- · ·						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Reverse camera and a/c working at inspection. Nav is Japan only						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~		1	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		1	
								1		
Inspecte	d by: Reuben Harvey					Date: 15 Apr 20	25			
I have read	and understood th	is condition c	juide. Name:			Signature:				