

Report ID: 26,733,777 2 Version: Created: 24 Apr 2025

| Make:  | Peugeot            | Model:               | 308                | Body Style:    | Hatchback    |                             | Pass   | Fail | N/A |
|--|--------------------|----------------------|--------------------|----------------|--------------|-----------------------------|--|------|-----|
| Year:  | 2014               | <b>Registration:</b> | HHM222             | Reg Expiry:    | 04 Jul 2025  | Engine                      | 1  | I    | 1   |
| WoF Expiry:  | 18 Feb 2026        | Odometer:            | 106,851 Kms        | Good No:       | 26733777     | Oil level                   | ~  |      |     |
| VIN:   | VF34C5FVADS112804  | Next Service:        | 114301             | Service Histor | <b>y:</b> No | Smoke & fumes               | V  |      |     |
|  |                    |                      |                    |                |              | Performance                 | V  |      |     |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or |                    |                      |                    |                |              | Noise                       | r  |      |     |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends   |                    |                      |                    |                |              | Cooling System              |  |      |     |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge.  |                    |                      |                    |                |              | Coolant condition           | ~  |      |     |
|  |                    |                      |                    |                |              | Performance                 | ~  |      |     |
| Key:   |                    | -0                   | SC SC              | -01-           |              | Radiator / Hoses (visual)   | ~  |      |     |
| S = scratch  |                    |                      |                    |                |              | Transmission                |  |      |     |
| D = dent<br>R = rurt   |                    |                      |                    |                |              | Operation                   | ~  |      |     |
| R = rust<br>PT = paint def   |                    |                      |                    | $\int$         | JHIH         | Noise                       | ~  |      |     |
| C = crack  |                    |                      |                    |                |              | Clutch                      |  |      | ~   |
| P = pin dent   |                    |                      |                    |                |              | CV joints                   | ~  |      |     |
| * = decals   | sc 916             |                      |                    | - AL           | EII PR-      | Wheel bearings              | ~  |      |     |
| SC = stone chips   |                    |                      |                    |                |              | Brakes                      | V  |      |     |
| W = significant scuffs   |                    |                      |                    |                |              | Performance                 | ~  |      |     |
| Note: come defects % blamiches may not be displayed in the diagram   |                    |                      |                    |                |              | Hand Brake                  | ~  |      |     |
| Body Inspection Comments   |                    |                      |                    |                |              |                             | <b>Trand Brake</b><br><b>Yres</b> (lowest observed tread depth of tyre |      |     |
| Headlights cloudy  |                    |                      |                    |                |              | Left front                  |  | .0   | mm  |
|  |                    |                      |                    |                |              |                             |  |      | -   |
|  |                    |                      |                    |                |              | Right front<br>Left rear    |  | .0   | mm  |
|  |                    |                      |                    |                |              |                             |  | .0   | mm  |
| Conditions During Body Inspection: Dry   |                    |                      |                    |                |              | Right rear                  | 4.0 mm   |      | mm  |
| Under Carriage & Under Bonnet Inspection Comments  |                    |                      |                    |                |              | Spare Yes                   |  |      |     |
|  |                    | meenspeede           | <u>on comments</u> |                |              | Suspension                  |  |      |     |
|  |                    |                      |                    |                |              | Suspension performance      | ~  |      |     |
|  |                    |                      |                    |                |              | Steering performance        | ~  |      |     |
|  |                    |                      |                    |                |              | Shock absorbers             | ~  |      |     |
|  |                    |                      |                    |                |              | Air Conditioning / Heater   |  |      |     |
| Interior Comments  |                    |                      |                    |                |              | Operation                   | ~  |      |     |
|  |                    |                      |                    |                |              | Electrical / Accessories    |  |      |     |
| Seats  | Good               |                      |                    |                |              | Head lights                 | ~  |      |     |
| Carpets  | Good               |                      |                    |                |              | Tail lights                 | ~  |      |     |
|  |                    |                      |                    |                |              | Indicators                  | ~  |      |     |
| Panels   | Good               |                      |                    |                |              | Dashboard warning lights    | ~  |      |     |
| Dashboa  | rd C               |                      |                    |                |              | Wipers (front & rear)       | ~  |      |     |
|  | rd Good            |                      |                    |                |              | Window winder FL            | ~  |      |     |
|  |                    |                      |                    |                |              | Window winder FR            | ~  |      |     |
| <u>General Comments</u>  |                    |                      |                    |                |              | Window winder RL            | ~  |      |     |
| A/c working at inspection. No reverse camera. 95 octane petrol   |                    |                      |                    |                |              | Window winder RR            | ~  |      |     |
|  |                    |                      |                    |                |              | Rear view mirrors           | ~  |      |     |
|  |                    |                      |                    |                |              | Radio (basic test only)     | ~  |      |     |
|  |                    |                      |                    |                |              | CD (basic test only)        | ~  |      |     |
|  |                    |                      |                    |                |              | Number of keys              | 2  |      |     |
| Road Conditions During Test Drive: Dry   |                    |                      |                    |                |              | Central locking             | ~  |      |     |
|  |                    |                      |                    |                |              | Remote locking              | ~  |      |     |
| Engine Timing Mechanism: Timing Chain  |                    |                      |                    |                |              | Sat. Nav. (basic test only) |  |      | ~   |
| Evidence   | of Cam Belt Replac | ement: N             | lot Applicable     | Kms:           |              | Reversing camera            |  |      | ~   |
|  |                    |                      |                    |                |              |                             |  |      |     |
| Inspected by: Reuben Harvey Date: 14 Apr 2025  |                    |                      |                    |                |              |                             |  |      |     |
| I have read and understood this condition guide. Name:   |                    |                      |                    |                |              |                             |  |      |     |