

Coolant condition V Radiator / Hoses (visual) V V V C = crackClutch V P = pin dent CV joints ~ SC * = decals S D Wheel bearings V SC = stone chips Brakes W = significant scuffs S Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front 10.0 mm **Right front** 10.0 mm Left rear 10.0 mm **Right rear** 10.0 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Head lights Seats 1 Drivers seat small hole Tail lights ~ Carpets No floor mats provided Indicators ~ Dashboard warning lights 1 Panels Good Wipers (front & rear) 1 Dashboard Good Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR 4WD V Rear view mirrors 1 Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera ~

Bobby Zhong Inspected by:

23 Apr 2025 Date:

I have read and understood this condition guide.

Name:

Signature:

Report ID: 26,735,791 Version: 1 24 Apr 2025

Pass

~

V

V

~

Fail

N/A

Created: