

Report ID: 26,735,817 3 Version: 29 Apr 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:	FYZ865	Reg Expiry:	09 Jul 2025	Engine	1	I	
WoF Expiry:	10 Feb 2026	Odometer:	193,620 Kms	Good No:	26735817	Oil level	~		
VIN:	7AT0C13JX11105647	Next Service:	203000	Service Histor	y: No	Smoke & fumes	V		
						Performance	r		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	SC S	A/	S S		S	Performance	~		
Key:	ISC [S	<u> </u>	S S	$-\square$		Radiator / Hoses (visual)			~
S = scratch						Transmission			
D = dent R = rust S PT S W						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 99						Wheel bearings			~
SC = stone chips						Brakes			
W = significant scuffs S S W S S PT S W S						Performance	~		
Redu Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres		
Left rear weather shield cracked						Left front 4.4			mm
						Right front		.9	mm
						Left rear		.3	mm
Conditions During Body Inspection:						Right rear		.8	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
No underbo	ody inspection					Steering performance	~		
						Shock absorbers			~
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights 🖌			
						Tail lights	~		
Carpets	Poor					Indicators	~		
Panels	Poor					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd dash boar	d cracked in cent	re by windscreen			Window winder FL	~		
	ľ					Window winder FR	~		
General Comments						Window winder RL	~		
Engine drive belts worn and noisey						Window winder RR	~		
Ignition barrel missing coverr						Rear view mirrors	~		
						Radio (basic test only)	V		
						CD (basic test only)	V		
						Number of keys	1	I	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
								1	1
Inspected by: Melissa Wilson Date: 29 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: