

Report ID: 26,735,919 1 Version: 24 Apr 2025 Created:

Make: Mazd	а	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year: 2007		Registration:	RCP837	Reg Expiry:	04 Jul 2025	Engine	I		L
WoF Expiry: 20 Jan	n 2026	Odometer:	111,541 Kms	Good No:	26735919	Oil level	~		
VIN: 7AT0	C12HX16111353	Next Service:	111541	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is			for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanical in	spection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
			C DT W			Performance	~		
Key:		<u>~</u> ⊘	S PT W S	-161-	SP	Radiator / Hoses (visual)	•		~
S = scratch	RE	A U			Ton .	Transmission			-
D = dent	- HE			TIN	S S	Operation	~		
R = rust PT = paint defect	—171P			\prod	JUIL	Noise	~		
C = crack	11			+		Clutch	-		~
P = pin dent	110				세비	CV joints	~		
* = decals	sc 6/6			- Jul		Wheel bearings	•		~
SC = stone chips						Brakes			
W = significant scuffs	S W	- V	S S		SD	Performance	~		
D. I. I		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspectio	on Comments			,		Tyres (lowest observed tread	-	of tyre	<u> </u>
						Left front 7 mm			
						Right front	7 mm		
						Left rear			mm
						Right rear			
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
No underbody ins	pection					Steering performance	~		<u> </u>
						Shock absorbers	V		~
						Air Conditioning / Heater			V
									<u> </u>
Interior Comments						Operation 🖌			
						Head lights			
Seats	Good					-	~		<u> </u>
Carpets	Good					Tail lights	~		
						Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboard	Good					Wipers (front & rear) Window winder FL	~		<u> </u>
						Window winder FL Window winder FR	~		<u> </u>
General Comm	nents					Window winder FR Window winder RL	~		<u> </u>
							~		
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	v		<u> </u>
						CD (basic test only)			L
	~ ·	~ .				Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		<u> </u>
		Normerite N		11113.		Reversing camera	~		
Inspected by: Melissa Wilson Date: 24 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: