

Report ID: 26,737,036 1 Version: 09 May 2025 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JLL635	Reg Expiry:	18 Aug 2025	Engine			L
WoF Expiry:		Odometer:	195,897 Kms	Good No:	26737036	Oil level	~		
VIN:	MMU143CK0GH620306	Next Service:	-	Service Histor		Smoke & fumes	~		
			200000		. 105	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust				10		Operation	~		
PT = paint def C = crack	ect			+	SC	Noise Clutch	~		
P = pin dent	LHE	KI			JUII ——		~		
* = decals	DSC PR			SI_	ANR -	CV joints			~
SC = stone chips						Wheel bearings	~		
W = significant scuffs PR						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<b>6</b> .	
Bonnet damaged top left corner and misaligned. Small dent in LH A pillar						Tyres (lowest observed tread depth of tyres)			
						Left front	7.0 mm		-
						Right front		.0	mm
[						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear	5.5 mm		mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa						Wipers (front & rear)	~		
Dashboa	Good. stee	ering wheel worr	1			Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
No keys for lock boxes						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		_
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
·	LL Devilence LL								
Inspected by: Reuben Harvey Date: 16 Apr 2025									
I have read and understood this condition guide. Name:									