

## **Basic Vehicle Condition Guide**

Report ID: 26,737,378


Version:

22 Apr 2025 Created:

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2018 Registration: LDY781 Reg Expiry: 13 Aug 2025 WoF Expiry: **Odometer:** 19 Apr 2026 58,743 Kms **Good No:** 26737378 VIN: KMHJ3814MHU436087 **Next Service:** 67000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Minor stone chips on windscreen

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Front wheel drive

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

15 Apr 2025 Jaykib Collins Inspected by: Date:

- Create			
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\( \times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5.5		mm
Right front	5.5		mm
Left rear	2.5		mm
Right rear	2.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	-		_
Number of keys	2		_
Central locking	- -		
Remote locking	~		
Sat. Nav. (basic test only)			1
Reversing camera	~		
eversing cumera			

I have read and understood this condition guide.

Name: .....

Signature: .....