

7AT0H64FX25011377

Basic Vehicle Condition Guide

Service History:

Report ID: 26,737,822

Version: 2

Created: 29 May 2025


Make: Model: Toyota Voxy **Body Style:** Wagon Year: 2014 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 07 May 2026 105,667 Kms 26737822

Next Service: 115,600 km

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

FWD,

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Genera	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Imraan Bryant Date: 12 May 2025

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7	.0	mm
Right front	7	.0	mm
Left rear	5.0		mm
Right rear	5.0		mm
Spare		N/A	
Suspension			
Suspension performance	V V		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	/		
Window winder FR	~		
Window winder RL	~		
Window winder RR	\(\times \)		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		

Signature: