

Report ID: 26,737,846 2 Version: 20 May 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2018	<b>Registration:</b>		<b>Reg Expiry:</b>		Engine	•			
WoF Expiry:	15 May 2026	Odometer:	81,899 Kms	Good No:	26737846	Oil level	~			
VIN:	7AT0GF09X25076335	Next Service:	91,896 kms	Service Histor	r <b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a run mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:						Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust PT = paint defect						Operation	~			
						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
*= decals						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
						Performance	~			
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)	
					Left front 7.0 m					
						Right front	7.	.0	mm	
						Left rear	7.	.0	mm	
Conditions During Body Inspection: Dry						Right rear	7.	7.0 mm		
Conditions During Body inspection. Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
4wd						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
L						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Seats Good					Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	·					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Remote							~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~			
Inspected by: Marlon Espena Date: 19 May 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....