

Report ID: 26,738,169 1 Version: 01 May 2025 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	NQG891	Reg Expiry:	16 Jul 2025	Engine			
WoF Expiry:	30 Apr 2026	Odometer:	64,870 Kms	Good No:	26738169	Oil level	~		
VIN:	WVWZZZ1KZAW337804	Next Service:	75,000	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Dauta hava u at	haan diamaanda daar	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SC S		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SC 6 6 5						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack					╫╫╢	Clutch	•		~
P = pin dent	Ho					CV joints	~		•
*=decals SC QQ						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: som	e defects & blemisbes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)))
						Right front			mm mm
						Left rear			
									mm
Conditions During Body Inspection: Dry						Right rear 6.5 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
<u></u>						Suspension performance			
							~		
						Steering performance Shock absorbers	~		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories Head lights			
Seats	Good						~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Roof lining	minor sag by sun glass	holder				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing (Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		.cmcnt. N		11113.		Reversing camera			~
Inspected by: Reuben Harvey Date: 16 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: