

Report ID: 26,738,992 1 Version: 24 May 2025 Created:

Make:	Toyota	Model:	Aqua	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>		Reg Expiry:		Engine	•	-	
WoF Expiry:	20 May 2026	Odometer:	32,556 Kms	Good No:	26738992	Oil level	~		
VIN:	7AT0H65YX25173988	Next Service:	42550	Service Histor	r <b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and u	his can be arranged to	or an additional of	charge.	Coolant condition	~		
			Р		S	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				10		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	PT dlP				2416	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7.0 mm		mm
Right from							6.0 mm		mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
						Spare	e Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
. Suspension performance						Suspension performance	~		
Steering performance							~		
Shock absorbers							~		
	Air Conditioning / Heater								
Operation							~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
Remote locking									
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Buckley Date: 23 May 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....