

Report ID: 26,739,135 1 Version: 20 May 2025 Created:

Make:	Subaru	Model:	XV	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine			
WoF Expiry:	16 May 2026	Odometer:	95,507 Kms	Good No:	26739135	Oil level	~		
VIN:	7AT0GF1XX25068116	Next Service:	105,600 Kms	Service Histor	r y: No	Smoke & fumes	~		
						Performance	~		
	oort is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	t been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged to	or an additional	charge.	Coolant condition	~		
					S	Performance	V		
Key:		-0		5(0)-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
B = rust	DW			710		Operation	~		
PT = paint defe	ect NP				10111	Noise	V		
C = crack					PT	Clutch			~
P = pin dent	HIP				74114	CV joints	V		
* = decals	- Alt	10		10		Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
	P					Performance	~		
Body Insr	ection Comments	Note: son	ne defects & blemishe	s may not be dis	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	6	.0	mm
						Right front	5	.8	mm
						Left rear	6	.5	mm
Conditions During Body Inspection: Wet						Right rear	6.5 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Stitching v	vorn on drivers s	eat lower cushion			Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ru Steering w	heel material pe	eling off			Window winder FL	~		
						Window winder FR	~		
General C	<u>comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Hoani Saunders Date: 19 May 2025									

I have read and understood this condition guide.

Name:

Signature: