

Report ID: 26,739,208 Version: 1 28 Apr 2025 Created:

Make:	Mercedes-Benz	Model:	B-Class	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2009	Registration:	EUD327	<b>Reg Expiry:</b>	21 Jun 2025	Engine		1		
WoF Expiry:	22 Apr 2026	Odometer:	110,632 Kms	Good No:	26739208	Oil level	~			
VIN:	WDD2452332J394582	Next Service:	120000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
	SC		SC SC		SC	Performance	~			
Key:		=		500-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
R = rust SC A A SC S						Operation	~			
PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent	D SC D SC				24116	CV joints	~			
						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
W = significant scurrs SC SC SC SC SC						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~			
						Tyres (lowest observed trea	(lowest observed tread depth of tyres)			
						Left front	7.5 mm		mm	
						Right front	5	.0	mm	
						Left rear	4	.0	mm	
Conditions During Body Inspection: Dry						Right rear	4	.0	mm	
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Rh outer cv	split					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
		Operation	~							
Interior Comments						Electrical / Accessories	-	-		
Seats	Good					Head lights	~			
Carpets	Coord					Tail lights	~			
	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Caral					Wipers (front & rear)	~			
	rd Good					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~		<u> </u>	
A/c and reverse camera working at inspection, 95 octane petrol						Window winder RR	~		<u> </u>	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>	
						Sat. Nav. (basic test only)			~	
Evidence	ог сапт вен, керіас	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Reuben Harvey						Date: 16 Apr 2025				
I have read and understood this condition guide. Name:										