

## **Basic Vehicle Condition Guide**

Report ID: 26,745,423


3 Version:

10 May 2025 Created:

Make: Model: Mazda Atenza **Body Style:** Wagon Year: 2008 Registration: JPE266 Reg Expiry: 12 Jul 2025 **Odometer:** WoF Expiry: 20 Dec 2025 161,783 Kms **Good No:** 26745423 VIN: 7AT0C139X15102760 Next Service: 171,000 Kms Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Vehicle is in good condition

**Conditions During Body Inspection:** Dry

## **Under Carriage & Under Bonnet Inspection Comments**

Electric side mirrors retract but do not adjust.

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## **General Comments**

Front wheel drive

Steering wheel controls not connected to radio

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Ariitea Raposo 08 May 2025 Inspected by: Date:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	es)
6.0		mm
	Yes	
~		
~		
~		
~		
<b>'</b>		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
2		
~		
~		
		~
		~
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	V

I have read and understood this condition guide.

Name			

Signature: .....