

Report ID: 26,746,453 3 Version: 15 May 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback	] [	Pass	Fail	N/A
Year:	2007	<b>Registration:</b>	LKQ838	<b>Reg Expiry:</b>	29 May 2025	Engine	1		
WoF Expiry:	30 Jan 2026	Odometer:	178,190 Kms	Good No:	26746453	Oil level	~		
VIN:	7AT0C13JX18317045	Next Service:	185640	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for any and milaage	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and t	his can be arranged f	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SDPT	-0	S P SC S P SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	PT SC W			The	BIN SDW	Operation	~		
R = rust					JHIH	Noise	~		
PT = paint defects C = crack				+	S PT SC	Clutch	•		~
P = pin dent	Htc	K I				CV joints	~		
* = decals	PT SC PK			AL	ELLAR SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SPT SP SDP DW						Performance	~		T
		Noto: con	ne defects & blemishe			Hand Brake			
Body Insp	pection Comments		le délects à biennisne	s may not be disp	nayed in the diagram				
Paint flaking. Paint has contamination. Front bumper poor fit						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front		.5	mm
						Right front		.5	mm
						Left rear	-	.0	mm
Conditions During Body Inspection: Dry						Right rear 5.0		.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			. <u> </u>
Battery pas	sed test.					Suspension performance	~		
						Steering performance		~	
						Shock absorbers	~		
						Air Conditioning / Heater		-	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ard Average					Window winder FL	~		
г	-					Window winder FR	~		
General Comments					Window winder RL	~			
A/c working at inspection.						Window winder RR	~		<u> </u>
						Rear view mirrors	~		1
						Radio (basic test only)	~		t
						CD (basic test only)	~		<u> </u>
						Number of keys	1	I	L
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-	~	<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera		•	~
		•							
Inspected by: Reuben Harvey Date: 22 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....