

Basic Vehicle Condition Guide

Report ID: 26,746,513


Version: 2

Created: 09 May 2025

Make: Model: Toyota Allion **Body Style:** Sedan Year: 2008 Registration: KSY787 Reg Expiry: 26 Jan 2026 **Odometer:** WoF Expiry: **Good No:** 23 May 2026 200,450 Kms 26746513 VIN: 7AT0H645X17021940 **Next Service:** 20/8/25 or 206000km **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Vehicle drove well. Rear wiper not working.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jayden Roxburgh

| Created | u | o iviay 2 | | |
|------------------------------|---|-----------|-----|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | V | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | V | | | |
| Hand Brake | ./ | | | |
| Tyres (lowest observed treac | l dopth | of tur |) | |
| Left front | | | - | |
| | | 5 | mm | |
| Right front | | 5 | mm | |
| Left rear | | 7 | mm | |
| Right rear | 9 | 9 | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | - | | | |
| Steering performance | ~ | | | |
| Shock absorbers 🗸 | | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | v v | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | | ~ | | |
| Window winder FL | ~ | | | |
| Window winder FR | VVV | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | • | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| L | | | | |

I have read and understood this condition guide.

Name:

Signature:

09 May 2025