

Report ID: 26,746,718 2 Version: 10 May 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Wagon		Pass	Fail	N/A
Year:	2007	Registration:	HGY492	Reg Expiry:	04 Jun 2025	Engine			
WoF Expiry:	26 Apr 2025	Odometer:	193,430 Kms	Good No:	26746718	Oil level	~		
VIN:	7AT0C13JX14309844	Next Service:	203,400	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
					s	Performance	~		
Key:	SC	-0	S SC P W	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack					SC PT	Clutch	•		~
P = pin dent						CV joints	~		
* = decals PT SC PIP						Wheel bearings	• •		
SC = stone chips						Brakes			
W = significant scuffs P SC S SC S SC P						Performance			
		Note: som		may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
Minor paint fade						Tyres (lowest observed tread depth of tyres)			
						Left front		.5	mm
						Right front		.5	mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear 8.0 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage a onder bonnet inspection comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	A					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Front door speaker covers damaged						Window winder RR	~		
Moisture in spare wheel well						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-								<u> </u>
Inspected by: Reuben Harvey Date: 22 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: