

Report ID: 26,747,750 2 Version: 06 May 2025 Created:

Make:	BMW	Model:	X1	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	MZB633	Reg Expiry:	22 Jan 2026	Engine			L
WoF Expiry:	24 Jun 2025	Odometer:	81,977 Kms	Good No:	26747750	Oil level	~		
VIN:	WBAVL32010VN77096	Next Service:	86200	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			S SC S SC		S SC	Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
W = significant scons S SC S P SC S SC S SC S SC						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.0 1		mm
						Right front	5.6		mm
						Left rear	4.1		mm
Conditions During Body Inspection: Dry						Right rear	4.9 mm		mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Two wheel drive						Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concerté	ommost.					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Oil Leak						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	ditions During Tes	Central locking	~						
	ning Mechanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
	or Cam Beil Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Cameron Senior-Arnold Date: 24 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: