

Report ID: 26,749,639 1 Version: 27 Apr 2025 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2013		GZS307	Reg Expiry:	31 May 2025	Engine			L
WoF Expiry:	22 Apr 2026	Odometer:	210,130 Kms	Good No:	26749639	Oil level	~		
VIN:	MR0GZ12G209001104	Next Service:	218000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
			S SC SC		S	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S AL			215	S SC	Operation	~		
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HIS				74 <u>11</u> 4	CV joints	~		
* = decals	M			The second	ELD'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = signincan	S		S SC SC		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments					Tyres (lowest observed tread depth of tyres)				
					Left front	6.	.8	mm	
						Right front	7.	.0	mm
						Left rear	5.	.8	mm
Conditions During Body Inspection: Dry						Right rear	5.9 m		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Two wheel drive						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
Carrasta						Tail lights	~		
Carpets	Good					Indicators	۲		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd C 1					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	<		
<b>F</b> ar at 1 = <b>7</b> <sup>1</sup>		<u> </u>				Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 15	0,021	Reversing camera			~
Inspected by: Cameron Senior-Arnold Date: 23 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....