

n Guide		Report ID:		26,750,706			
		Version:		4			
		Created:		26 Jun 2025			
			Pass	Fail	N/A		
	Engine						

V

VIN: WVGZZZ5NZ	LW808771 Next Service:	97,750kms	Service History: No	Smoke & fumes	~					
				Performance	~					
Note: This report is not This report is a guide of	Noise	~								
diagnostic testing unde	rtaken. The vehicle has beer tion prior to purchase and th	Cooling System								
a full mechanical inspec	Coolant condition	~								
		P		Performance	~					
Key:			50-	Radiator / Hoses (visual)	~					
S = scratch	Transmission									
D = dent R = rust		Operation	~							
PT = paint defect	NMF	Noise	~							
C = crack		Clutch			~					
P = pin dent	110	CV joints	~							
* = decals	HIR	Wheel bearings	~							
SC = stone chips	12 (0)	Brakes								
W = significant scuffs		Performance 🖌								
	Note: som	ne defects & blemish	es may not be displayed in the diagram	Hand Brake	~					
Body Inspection C	<u>omments</u>		,	Tyres (lowest observed tread depth of tyres)						
	Left front 6.5 m									
	Right front		.5	mm						
				Left rear		.0	mm			
Conditions During	Podulaspostion	D.		Right rear		.0	mm			
Conditions During	у войу іпѕресцоп:	Dry		Spare	5	Yes				
Under Carriage &	Under Bonnet Inspectio	on Comments		Suspension						
	Suspension performance	~								
	Steering performance	~								
				Shock absorbers	~					
	Air Conditioning / Heater									
	Operation									
Interior Comment	Electrical / Accessories									
Seats Good				Head lights	~					
				Tail lights	~					
Carpets	Good			Indicators	~					
Panels	Card			Dashboard warning lights	~					
	Good			Wipers (front & rear)	~					
Dashboard	Good			Window winder FL	~					
	I			Window winder FR	~					
General Commen	Window winder RL	~								
	Window winder RR	~								
	Rear view mirrors	~								
	Radio (basic test only)	~								
	· · · · · · · · · · · · · · · · · · ·			~						
		CD (basic test only)	2		~					
	Number of keys 2									
Road Conditions D	Central locking	v								
Engine Timing Me	Remote locking	~								
Evidence of Cam B	Sat. Nav. (basic test only)			~						
	elt Replacement: N	Reversing camera	~							
Inspected by: Yuki Itohara Date: 20 May 2025										

I have read and understood this condition guide.

Name:

Signature: