

Report ID: 26,751,350 9 Version: Created: 17 Jun 2025

Make:	Ford	Model:	Escape	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	Registration:	LRA903	Reg Expiry:	01 Oct 2025	Engine	1		1
WoF Expiry:	12 May 2026	Odometer:	112,805 Kms	Good No:	26751350	Oil level	~		
VIN:	WF0AXXWPMAHA26749	Next Service:	122000	Service Histor	y: No	Smoke & fumes	V		
						Performance	V		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	V		
	S					Performance	V		
Key:	L'ALL	-0		-01-		Radiator / Hoses (visual)	V		
S = scratch						Transmission	I		1
D = dent R = rust	SC DI			715	HIVP	Operation	~		
PT = paint def	ect NP	FI		$\left(\left \right\rangle \right)$		Noise	r		
C = crack					SC	Clutch			~
P = pin dent	HIC				7414	CV joints	r		
* = decals	sc 816			-No-	AD w	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Dedulae		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
Hole in rear bumper						Left front 4.5 mm			
						Right front	4	-	mm
						Left rear	6		mm
Conditions During Rody Inspections						Right rear	6	-	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Battery pas	sed test.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
		Operation	~						
Interior Comments						Electrical / Accessories			<u> </u>
Seats Good						Head lights	~		
						Tail lights	v		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		+
						Window winder FR	~		+
General Comments						Window winder RL	~		+
A/c, reverse camera and nav working at inspection						Window winder RR	~		+
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		1
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
	•						-		1
Inspecte	d by: Reuben Harvey					Date: 24 Apr 20	25		
I have read	and understood th	is condition c	juide. Name: .			Signature:			