

Report ID: 26,751,619 3 Version: 06 May 2025 Created:

Make:	Mini	Model:	Cooper	Body Style:	Hatchback	וך		Pass	Fail	N/A	
Year:	2009	Registration:	HSN100	Reg Expiry:	02 Jul 2025		Engine				
WoF Expiry:	18 Jun 2025	Odometer:	183,012 Kms	Good No:	26751619		Oil level	~			
VIN:	WMWMF72070TT43535	Next Service:	195000	Service Histor	y: Yes		Smoke & fumes	~			
							Performance		~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
	P S	W	S P	S	SC	ו	Performance	~			
Key:							Radiator / Hoses (visual)			~	
S = scratch D = dent							Transmission		1		
D = dent R = rust S SC							Operation	~			
PT = paint defect NIM							Noise	~			
C = crack							Clutch	~			
P = pin dent							CV joints	~			
* = decals SDSC 919							Wheel bearings			~	
SC = stone chips							Brakes				
W = significant scuffs S D S W S P							Performance	~			
Note: some defects & blemishes may not be displayed in the diagram							Hand Brake	~			
Body Inspection Comments							Tyres (lowest observed tread	depth	of tyre	es)	
Brush marks/ scratches on roof							Left front	. 5	.9	mm	
							Right front		.6	mm	
							Left rear		.7	mm	
Conditions During Pody Inspections Day						٦	Right rear			mm	
Conditions During Body Inspection: Dry							Spare No				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
							Suspension performance	V			
No underbody inspection carried outt							Steering performance	v			
							Shock absorbers	•		~	
							Air Conditioning / Heater			•	
							Operation				
Interior Comments							Operation 🖌				
							Head lights	~			
	Average						Tail lights	~			
Carpets	Good						Indicators	~			
							Dashboard warning lights				
Panels	Average						Wipers (front & rear)	レ レ			
Dashboa	rd Average						Window winder FL				
							Window winder FL	~			
General (Comments					ור	Window winder RL	v			
							Window winder RE	V			
Missing un	der acceleration							~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	1	~		
						╡	Number of keys	1			
Road Conditions During Test Drive: Dry							Central locking	~			
Engine Ti	ming Mechanism:	Unknow	/n			וך	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
	or cam beit neplat	ement. p		11113.			Reversing camera			~	
Inspected by: Melissa Wilson Date: 06 May 2025											

I have read and understood this condition guide.

Name:

Signature: